

AUCTION ARBITRATION RISK REPORT

Auction Risk Intelligence | RPT.K5651 | VIN 1HGCV3F15JA002503

VIN 1HGCV3F15JA002503	VEHICLE 2018 / HONDA / Accord	AUCTION Manheim New York	SCOPE Vehicle DTCs
OVERALL RISK MEDIUM Auction review recommended	SCORE 38/100 Combined risk metric	WARNING LIGHT - Active warning indicator	
EXECUTIVE DECISION SUMMARY Current engine oil pressure sensor code with moderate repair estimate and warning light ON indicates possible dispute risk.			ACTION Disclosure check recommended before release; mechanical review may be considered.

Auction Inspector Decision Points

- Do not treat as a pass-through vehicle without review: warning light is - and all high-risk DTCs are current.
- Focus inspection on root cause analysis for codes: .
- Review sale disclosure before release: repair estimates contain multiple high-risk exposure items.
- PSI / mechanic should verify drivability, communication modules, fuel system, and transmission operation.
- Review diagnostic confidence indicators and confirm repair history before release.

Root-Cause Risk Map

Code	Risk	Score	NAAA Category	Root Cause Focus	Cost Range	Inspector Action
P0523	MEDIUM	38	Engine Problem	Engine Problem	\$77-\$245	Disclosure check recommended; mechanical review may be considered.

NAAA Review Triggers

Operational review triggers only. This report does not make a legal arbitration determination.

Trigger	Why It Matters	Auction Decision
Moderate repair cost engine sensor fault	Potential drivability or engine damage risk if sensor or wiring issue is unresolved.	Disclosure check recommended; consider mechanical review.

Baseline Metrics for Management

Combined Score	Highest Score	High Codes	Critical Codes	\$800+ Flags	Current Codes
38 / 100	38	0	0	0	1

Recommended Auction Workflow

1

Hold for Review

Flag vehicle for mechanical / PSI review before buyer release.

2

Verify Root Cause

Focus on drivability, communication modules, fuel system, and transmission operation.

3

Check Disclosure

Confirm warnings and repair exposure are reflected in sale notes.

4

Document Outcome

Save review notes with scan record for audit trail and seller/buyer clarity.

Executive Bottom Line

MEDIUM RISK - REVIEW BEFORE SALE / RELEASE

Current engine oil pressure sensor code with moderate repair estimate and warning light ON indicates possible dispute risk.