



Report ID: RPT.Q6750
User ID: demo@prestigeautocorp.com
07-21-2026@ 6:34 PM



Vehicle Info
2019 CHEVROLET Traverse
1GNEVHKW5KJ256873

Mileage
Dashboard: 73796 Miles
ECU/Multi-Module: 70800 Miles



CURRENT DTC CODE
[5 CODE(S) FOUND]



STANDARD SCAN
[PASS]



ADVANCED OEM SCAN
[PASS]



WARNING LIGHT
[ON]



EMISSIONS TEST
[PASS]



RECENT CODE RESET
[NOT FOUND]

CarDr Sales Agent Acc.
1 Mid America Plaza 3rd Floor, Suite
3066 Oakbrook
Illinois, Terrace, 60181

SCAN SUMMARY REPORT



\$1,370
Total Repair Estimate



5
Number of Current DTC Codes Found



40730 Miles
Distance Since Code Cleared



22
Number of OEM Modules Scanned

CODE SUMMARY

CURR

CURRENT

CONF

CONFIRMED

PERM

PERMANENT

HIST

HISTORIC

PEND

PENDING

CURR

ACTIVE REPAIR RISK: The ECU is actively detecting the fault. Repair exposure is immediate.

CONF

VERIFIED REPAIR EXPOSURE: Validated through multiple occurrences. May not be active now, but the repair exposure is real.

PERM

PERMANENT CODE INDICATOR: The ECU has not completed the validation cycle needed to clear the stored.

HIST

HISTORICAL EVENT: The fault occurred previously. No evidence it remains active.

PEND

EMERGING RISK: The ECU detected a developing issue. Additional validation is required.

ATTENTION

This list of codes have been detected & categorized as critical codes which require attention.

		Parts	Labor Hrs. Labor Cost		Total
CURR	 Engine Control Module P0442 Evaporative Emission Evap System Small Leak Detected	\$50.0 - \$250.0	1.0 - 2.0	\$95.0 - \$190.0	\$145.0 - \$440.0
HIST					
PARTS INFORMATION (QTY: 4)					
EVAP purge valve		EVAP canister vent valve		Fuel tank pressure sensor	
Fuel filler cap		CRITICALITY		COMMONALITY	
		LOW		Common	
IMPACT					
May Cause Increased Emissions; No Immediate Drivability Impact					
CURR	 Instrument Panel U0159 The Instrument Panel Ecu Has Lost Communication With The Parking Assist Control Module A, Indicating A Wiring Or Module Fault.	\$300.0 - \$1200.0	1.5 - 3.0	\$142.5 - \$285.0	\$442.5 - \$1485.0
PARTS INFORMATION (QTY: 4)					
Parking Assist Control Module A		Instrument Panel ECU		Wiring Harness	
Connector		CRITICALITY		COMMONALITY	
		HIGH		Uncommon	
IMPACT					
Parking Assist Features May Be Disabled, Affecting Parking Safety And Convenience.					
CURR	 Instrument Panel U1510 Lost Communication With Hvac Control Module	\$150.0 - \$900.0	1.5 - 3.0	\$142.5 - \$285.0	\$292.5 - \$1185.0
PARTS INFORMATION (QTY: 4)					
HVAC control module wiring harness		HVAC control module			
Instrument panel connector		ECU reprogramming		CRITICALITY	
				COMMONALITY	
		HIGH		Uncommon	
IMPACT					
Hvac System May Not Operate Correctly, Affecting Cabin Comfort					
CURR	 Radio U15E1 Loss Of Communication With The Radio Control Module Detected, Possibly Due To Wiring Or Connector Issues	\$150.0 - \$600.0	1.0 - 2.0	\$95.0 - \$190.0	\$245.0 - \$790.0
PARTS INFORMATION (QTY: 4)					
Radio control module		Radio wiring harness		Radio antenna	
Connector repair kit		CRITICALITY		COMMONALITY	
		LOW		Uncommon	
IMPACT					
Radio And Audio System May Not Function Properly					
CURR	 Radio U2098 Loss Of Communication Between Radio And Rear Seat Entertainment Module Detected	\$150.0 - \$700.0	1.0 - 2.0	\$95.0 - \$190.0	\$245.0 - \$890.0
PARTS INFORMATION (QTY: 4)					
Rear seat entertainment module		Radio head unit		Wiring harness	
Connector		CRITICALITY		COMMONALITY	
		LOW		Uncommon	

IMPACT

Rear Seat Entertainment May Not Function Properly; No Effect On Vehicle Drivability

EMISSION TEST



PASS

- ✓

Misfire
- ✓

Fuel System
- ✓

Components
- ✓

EGR/VVT System
- ✓

Oxygen Sensor Heater
- ✓

O2 Sensor
- ✓

Evaporative System
- ✓

Catalyst

DTC CODE RESET



NO Recent Reset Found.

DISTANCE SINCE CODES CLEARED (Miles) 40730

WARM UP CYCLES SINCE CODE CLEARED 255

VEHICLE DETAILS

ABS Standard	AirBagLocCurtain All Rows	AirBagLocFront 1st Row (Driver and Passenger)
AirBagLocSide 1st Row (Driver and Passenger)	AutoReverseSystem Standard	BasePrice 40295.00
BlindSpotMon Standard	BodyClass Sport Utility Vehicle [SUV]/Multipurpose Vehicle [MPV]	BrakeSystemType Hydraulic
BusFloorConfigType Not Applicable	DisplacementCI 219.68547874103	DisplacementL 3.6
Doors 4	DriveType AWD/All-Wheel Drive	EngineConfiguration V-Shaped
EngineCylinders 6	EngineManufacturer GM	EngineModel LFY - Spark Ignited Direct injection, ATSS, GEN 1
FuelTypePrimary Gasoline	GVWR Class 2E: 6,001 - 7,000 lb (2,722 - 3,175 kg)	KeylessIgnition Standard
Make CHEVROLET	Manufacturer GENERAL MOTORS LLC	Model Traverse
ModelYear 2019	MotorcycleSuspensionType Not Applicable	PlantCity LANSING - DELTA TOWNSHIP
PlantCompanyName GMNA	PlantCountry UNITED STATES (USA)	PlantState MICHIGAN
RearVisibilitySystem Standard	SeatBeltsAll Manual	SeatRows 3
Seats 7	SemiautomaticHeadlampBeamSwitching Standard	SteeringLocation Left-Hand Drive (LHD)
TPMS Direct	TractionControl Standard	TrailerBodyType Not Applicable
TrailerType Not Applicable	Trim LT	Trim2 Leather
VIN 1GNEVHKW5KJ256873	ValveTrainDesign Dual Overhead Cam (DOHC)	VehicleType MULTIPURPOSE PASSENGER VEHICLE (MPV)
WheelBaseShort 120.90	WheelSizeFront 18	WheelSizeRear 18
Wheels 4		