

AUCTION ARBITRATION RISK REPORT

Auction Risk Intelligence | RPT.K5194 | VIN 3N1CN7AP6HL907677

VIN 3N1CN7AP6HL907677	VEHICLE 2017 / NISSAN / Versa	AUCTION Manheim New Jersey	SCOPE Vehicle DTCs
OVERALL RISK MEDIUM Auction review recommended	SCORE 38/100 Combined risk metric	WARNING LIGHT OFF Active warning indicator	
EXECUTIVE DECISION SUMMARY Warning light status: OFF; current ABS Problem code C1130 with estimated repair cost midpoint \$500.00 indicates possible dispute risk.			ACTION Mechanical review and disclosure check recommended before release.

Auction Inspector Decision Points

- Do not treat as a pass-through vehicle without review: warning light is OFF and all high-risk DTCs are current.
- Focus inspection on root cause analysis for codes: .
- Review sale disclosure before release: repair estimates contain multiple high-risk exposure items.
- PSI / mechanic should verify drivability, communication modules, fuel system, and transmission operation.
- Review diagnostic confidence indicators and confirm repair history before release.

Root-Cause Risk Map

Code	Risk	Score	NAAA Category	Root Cause Focus	Cost Range	Inspector Action
C1130	MEDIUM	38	ABS Problem	ABS / wheel-speed / stability control	\$150-\$850	Mechanical review recommended due to ABS system impact.

NAAA Review Triggers

Operational review triggers only. This report does not make a legal arbitration determination.

Trigger	Why It Matters	Auction Decision
Current ABS Problem code with repair estimate midpoint \$500+	ABS issues can affect braking performance and safety, requiring review.	Mechanical review recommended

Baseline Metrics for Management

Combined Score	Highest Score	High Codes	Critical Codes	\$800+ Flags	Current Codes
38 / 100	38	0	0	0	1

Recommended Auction Workflow

1

Hold for Review
Flag vehicle for mechanical / PSI review before buyer release.

2

Verify Root Cause
Focus on drivability, communication modules, fuel system, and transmission operation.

3

Check Disclosure
Confirm warnings and repair exposure are reflected in sale notes.

4

Document Outcome
Save review notes with scan record for audit trail and seller/buyer clarity.

Executive Bottom Line

MEDIUM RISK - REVIEW BEFORE SALE / RELEASE
Warning light status: OFF; current ABS Problem code C1130 with estimated repair cost midpoint \$500.00 indicates possible dispute risk.